

Condition Assessment of a 100-year Old Well Station

City of Spokane Hoffman
Well Station

AWWA PNWS Annual Spring
Conference

Tacoma, WA

April 27-29, 2022



Hoffman Well Station, photograph by Charles Libby 1957.




Presentation Focus

- **Hoffman Well Station**

- Two open caisson production wells
- Constructed in 1920 as supply source for Great Northern Railway
- City acquired in 1938
- Well 2 out of service since 1993


- **Objective**

- Determine if (and to what extent) repairs are needed to bring Well 2 back online



Presentation Outline

- Introduction
 - Background
- Hoffman Well Station
 - Well construction
- Existing Conditions
 - Well 1
 - Well 2
- Repair Alternatives Evaluated
- Concept Plan for Selected Alternative






Introduction


Water System History

- City of Spokane water service began circa 1883
 - Water source = Spokane River
- Groundwater encountered in 1894 during construction of Upriver Dam and rediscovered in 1905
- City began transitioning to groundwater in 1907 due to poor surface water quality
- Well Electric Well Station, Wells 1 and 2



Well Electric WS Well 1


- Offline and preserved as an educational/historical display
- Capacity = 56 mgd
- City permanently discontinued use of river as its municipal supply source
- Five caisson wells constructed at the site over the years
- Wells 2 and 3 decommissioned
- Wells 4 and 5 remain in operation today




Water System Today

Legend

-  Well Sites
-  Reservoirs
-  City of Spokane Boundary
-  Water Retail Service Area
-  Transmission Mains



CITY OF SPOKANE WATER SYSTEM TODAY



AVERAGE PERCENT OF WATER PRODUCED BY CITY WELL STATIONS





Figure 9. Average percent of the City's water supply produced by City well stations during years 2007 through 2018.

SVRP Aquifer

- Spokane Valley – Rathdrum Prairie (SVRP) Aquifer
- Exclusive source of water supply for City
- Unconfined, highly productive, and highly transmissive
 - Production rates up to tens of millions of gallons per day
 - Hydraulic conductivity of 2,500 to 3,000 feet per day; 15,000 feet per day in some areas
- Underlain and laterally bounded by bedrock and low-permeability clay (Latah FM)
- Recharge primarily from infiltration of rainfall and snowmelt runoff and seepage from surface water bodies





Hoffman Well Station

Hoffman Well 1


- 6- to 16.5-foot diameter caisson well dug to 215 feet
- Currently operational
- Production capacity \approx 5,500 gpm
- Specific capacity \approx 815 gpm/foot of drawdown

Hoffman Well 2

- 6- to 10.5-foot diameter caisson well dug to 230 feet
- Well taken offline and pumping system removed in 1993
- Past production capacity \approx 5,500 gpm

Well Construction

- Two wells: Well 1 and Well 2
- Upper brick-lined, bell-shaped caisson; lower perforated steel casing
- Supplies water to North Hill PZ
- Total well station production capacity \approx 11,000 gpm
- SWL \approx 185 feet bgs
- No documentation of surface seal





Existing Conditions

Condition Assessment

- Objectives:
 - Characterize existing conditions
 - Verify well construction information
 - Evaluate facility modifications needed to access existing wells for repair/alteration
- Approach/Methods:
 - Compiled and reviewed available data
 - e.g., well/building construction, well performance, pumping rates, water levels, prior studies, etc.
 - Identified data gaps and prepared field investigation
 - Completed above- and below-water surveys, using personnel and underwater methods
 - Completed above-water visual structural inspections
 - Conducted 3D laser mapping survey



Condition Assessment – Findings

Well 1:

- Currently operational
- Visible portions of brick caisson appear in generally good condition
- Some missing bricks, likely remnants of old platform framing
- Areas of possible deformation in roundness of caisson wall, patched with mortar
- Pumping system obstructed access for below-water video surveys




Condition Assessment – Findings

Well 2:

- Offline since 1993 and not equipped with pumping system
- Some cracks in brick caisson wall observed at a few locations
 - Up to 1-1½ inches wide with some to no surface offset
 - Some cracks filled with black mortar
- Middle section of caisson wall contained a few hairline cracks
- Some evidence of past minor water seepage; no active seepage was observed at the time of the survey.
- Bell of caisson coated with gunite
- Some minor deformation has taken place since 1993 inspection, particularly in the middle and lower portions
- Minor encrustation of casing perforations
- Generally in good condition overall



Well 2 Brick Caisson Wall




Well 2 Perforated Casing



Repair Alternatives Evaluated


Alternative 1 – Line Brick Caisson Wall

- Fabric-Reinforced Cementitious Matrix (FRCM)
 - Composite lining for structural support
 - Two-layer grid system:
 - 1/2-inch cementitious matrix
 - Carbon fiber reinforced grid w/ strong axis vertically oriented
 - Second layer of 1/2-inch cementitious matrix
 - Carbon fiber reinforced grid w/ strong axis horizontally oriented
 - Final layer of 1/2-inch cementitious matrix
- Install new pump column and existing pump/motor
- Will improve structural integrity of the caisson and prevent water intrusion
- Planning-Level Cost (2018):
 - \$770,000 - \$1,645,000




Alternative 2 – Install and Seal Casing Liner Extension

- Install 3-5-foot diameter steel casing liner
- Extend casing liner inside existing 5-foot diameter casing
- Bottom portion of liner equipped with formation packers and steel coupler
- Seal coupler and base of liner extension with concrete and let cure
- Fill remaining annular space with grout seal in short lifts and let cure
- Install new pump column and existing pump/motor
- Will improve structural integrity of the caisson and prevent water intrusion
- Planning-Level Cost (2018):
 - \$855,000 - \$1,830,000



Alternative 3 – Crack Monitoring

- Use transducers to continuously monitor 3D displacement over time to understand:
 - Settlement/deformation rates
 - How external forces may be contributing to observed deformation (e.g., pump/motor operations)
- Install new pump column and existing pump/motor
- Assess whether to continue using Well 2, or implement alternative repair option
- Will not improve structural integrity of the caisson or prevent water intrusion
- Planning-Level Cost (2018):
 - \$405,000 - \$870,000





Concept Plan for Selected Alternative


Alternative 2 – Install and Seal Casing Liner Extension

Hoffman Well 2



Preferred Alternative

- Preferred repair alternative:
 - Install casing liner and extend to surface
 - Seal the annular space
- Uncertainty:
 - Will there be enough clearance for an adequate seal?
- Needed to conduct a plumbness and alignment test
- Traditional P/A test methods not valid
- Traffic accident reconstructionist and certified forensic photographer to the rescue!
 - Jeremy Bauer, Bauer Forensics, LLC



Alternative 2 – Install and Seal Casing Liner Extension

Hoffman Well 2



Plumbness and Alignment Test Results

Brick caisson wall near
top of perforated well
casing (approx. 10.5
feet in diameter)

Top of 5-foot
dia. perforated
casing



Base of caisson near top
of perforated casing

x : m y : m z : m




Alternative 2 – Install and Seal Casing Liner Extension

Hoffman Well 2



Plumbness and Alignment Test Results



Alternative 2 – Install and Seal Casing Liner Extension

Hoffman Well 2




Plumbness and Alignment Test Results

A – TOP VIEW OF CAISSON NEAR ACCESS LANDING

Inner brick caisson wall
near access landing

Top of
perforated
casing

Projection of new 3-foot
diameter casing liner




B – BOTTOM VIEW AT BASE OF CAISSON NEAR TOP OF
PERFORATED CASING

Inner brick caisson wall near
top of perforated casing

Top of
perforated
casing


Projection of new 3-foot
diameter casing liner



Hoffman Well 2



-
- SHAFT LINER = 6 PUMP SHAFT
- VERIFY
- 6 E15-0" STEEL COLUMN
- 3'-0" SHAFT LINER
- PUMP SHAFT, SEE CIVIL
- C.P.
- 4" MIN
- 2 #5, 3'-6" HOOP REINF
- 3 #5, 6'-6" HOOP REINF. SEE NOTE I
- 3 #5, 9'-6" HOOP REINF. SEE NOTE I
- 14 #4 TIE EVENLY SPACED (APPROX. 1'-6" OC @ 6'-6" HOOP)
- 5'-6"
- 6" CLR
- 7'-10 1/4" x 0.375" REDUCING PIPE CTR ON 3'-0" SHAFT LINER
- SEAL
- BRG 18x3.5'-2" I.D.
- 1' CLR
- 4'-0" THICK STRUCTURAL CONC PLUS
- (P) CAISSON BELL WALL
- SHAFT LINER = 6 PUMP SHAFT
- 6 E15-0" COLUMN
- (P) 5'-0" PERFORATED STEEL COLUMN
- 4'-5"
- 4'-5"
- 4'-5"



Alternative 2 – Install and Seal Casing Liner Extension


Hoffman Well 2



Preferred Alternative

Progress update:


- Currently in Construction
- Project Bid: June 2021
- Final Design: City of Spokane Engineering Services
- Low Bid: LARIVIERE INC
- City Engineers Estimated Cost: \$2,635,821.00
(Low Bid \$2,407,635.00)



Acknowledgements



murraysmith





Questions?

Kenny Janssen RG/LG, GSI Water Solutions, Inc.
kjanssen@gsiws.com

Joe Foote PE, Murraysmith, Inc.
Joe.Foote@murraysmith.us

Hoffman Well Station, photograph by Charles Libby 1957.