

Water Supply Well Condition Assessments

Real-World Applications and Results



Presented by Kevin Lindsey and Phil Brown;
with support of Steven Patten, Frank
Nicholson, Julie West, and Jon Travis

PNWS-AWWA Annual Conference
May 3-5, 2023

GEOENGINEERS 


 Northwest
Groundwater
Services, LLC

Introduction

- Purpose: Describe an Approach to Assessing Well Conditions and Look at Case Studies with Different Outcomes
- Outline:
 - Where are we
 - Types of wells
 - Methodology
 - Case studies
 - Take homes



Project Locations



Base modified from U.S. Geological Survey digital data, 1:2,000,000, 1972

EXPLANATION

- Columbia Basin Irrigation Project
- Odessa-Lind pumping center
- Columbia Plateau aquifer system study area
- Boundary of physiographic subprovince
- Boundary of Columbia Basin Ground Water Management Area (GWMA)



LOCATION OF STUDY AREA



The Wells

- 7 recent/ongoing well projects
- 6 are CRBG wells
- 6 are > 30 yrs
- 3 are open basalt completions
- 3 have long-term WL declines
- 2 not purpose-built for municipal supply



Methodology: Background

STATE OF WASHINGTON
DEPARTMENT OF CONSERVATION
DIVISION OF WATER RESOURCES

WELL LOG P-6900

Record by: Driller

Source: Driller's Record

Location: State of WASHINGTON

County: Lincoln

Area: _____

Map: _____

NW ¼ SE ¼ sec. 8 T. 21 N., R. 33 E.

Drilling Co.: Jasper Jones

Address: _____


Method of Drilling: Cable Date: Feb. 3, 1966

Owner: Town of Odessa

Address: Odessa, Washington

Land surface, datum: 1690 ft above

SWL: 360' Date: Feb. 3, 1966 Dims.: x 595'



PUMP TEST FORM
DATA SHEET
Page 1 of 2

WELL LOG #	WELL TAG #	WELL NAME OR #	DATE	ORIGINAL	DATE DILLED	TEST DATE
	APR-450	ESTERDAHL	1993	EASTERDAY	2-19-66	2-3-21
		BARABES INC.		BARABES INC.		BARABES PUMP CO.

Date	Time	Time Since Pumping Started (min)	Depth to Water Below MP	Discharge Rate (gpm, cfs, l)	Phase (Pre-Test, Pumping, Recovery)	Airline or Shut-in Pressure (psi)	Flowmeter Reading (if available)	Comments
2-3-21	11:01	1	UNKNOW	300	Pre-test	NONE		42.5 FE DEPTH
	11:01	20	300	300	Pre-test	140 PSI		40 PSI
	11:02	30	300	300	Pre-test			40 PSI
	11:40	40	275	275				40 PSI
	11:45	55	275	275		140 PSI		30 PSI
	11:50	50	275	275				30 PSI
	11:55	65	275	275				30 PSI
	12:00	60	280	280		140 PSI		20 PSI
	12:10	70	280	280				20 PSI
	12:20	80	280	280		140 PSI		20 PSI
	12:30	90	280	280				20 PSI
	12:40	105	280	280				20 PSI
	1:00	120	280	280				20 PSI
	1:10	130	280	280				20 PSI
	1:20	140	280	280				20 PSI
	1:30	150	280	280				20 PSI
	1:40	160	280	280				20 PSI
	1:50	170	280	280				20 PSI
	2:00	180	280	280				20 PSI
	2:10	190	280	280				20 PSI
	2:20	200	280	280				20 PSI
	2:30	210	280	280		130 PSI		
	2:40	220	280	280				

PUMP MAINTAINED A GOOD FLOW THROUGHOUT THE TESTING. REACTION IN LEVEL DUE TO AN INCREASED PUMPING RATE WAS UNABLE TO INSTANTANEOUSLY MONITOR. DESIGN - SPECIFICATION PROVIDED ASSUMES A PUMP HEAD OF 400'. 4" COLUMN PIPE 1.5 HP 240V 3PH SUBMERSIBLE MOTOR.

- Records Review:
 - Pumping
 - Water level
 - Chemistry
 - Well logs
 - Rebuild logs
 - What's been done; History

CONSTRUCTION	MATERIAL	From (feet)	To (feet)
			0 593
	Municipal use		
	WELL LOG (See attached sheet)		
	Casing: 16" from 0 to 250'		
	Surface sealed with concrete to a depth of 250'		
	Yield: 1200 gpm w/25' dd 8 hrs		
	Temp: 58		
	Pump: 125 h.p. Byron Jackson submersible		

Additional forms can be obtained from our web site at: <http://www.dnr.wa.gov/Forms/Forms.htm> CWDR 2004/15

Methodology: Background

- Wellhead Visit
 - Physical layout
 - Can we do what we want to do?
 - How are we going to do it



Methodology: Biogeochemical Profile

- Water Systems Engineering, Inc.
- WQ Sampling: Pump-on (in-well), 1 hr (aquifer)
- Biology:
 - Aerobic, anaerobic, genus/species
 - Activity
- Geochemistry:
 - Mechanical
 - Natural



Methodology: Biogeochemical Profile

- Geochemistry:
 - ORP/LSI/Hardness
 - Iron
 - TOC/Silica

- Biology:
 - Heterotrophic plate count
 - ATP (initial/growth)
 - Anerobic/aerobic (sulfate reducing/iron oxidizing species)
 - E-coli/coliform/protozoa

- Interpretation:
 - Surface/in-well/aquifer
 - Food source(s)
 - Rehab/disinfection options

Methodology: Physical Assessment

- Specific Capacity; current vs past
- Pull pump; column/pump conditions
- Video; What's there and where is it



Methodology: Analysis

- Goal: Simple cleanout, aggressive rehab/rebuild, or replace?
- Can well be rehabbed?
- Cleaning:
 - Chlorine or Acid
 - Swab/Brush
 - Pulse/Energy
- Reconstruction; if needed is it feasible?
- WQ improvement potential
- Risk/cost/benefit rehab vs replace decision



Case studies; Recent/Ongoing projects

- Grouped wells based on outcome
 - WW-7, WR-10
 - WW-5, Lind 7
 - WR-2, WR-3, MF-9

- For each examine
 - Current conditions
 - Construction history
 - Evaluation Findings
 - Outcomes and why



Case Studies: WW 7

- 50 y.o., unused for 30 years
- History of warm water with H₂S
- Power surcharge to start motor, so not exercised
- Building demolition required to pull pump
- PP&L Requested system test late 2022



Case Studies: WW 7


- The motor ran, and water was pumped (2,700 gpm)
- Biological profile showed low activity
- H₂S was not noted
- Water cleared in 5 minutes
- Specific capacity had not declined
- Take-Away: Even though this well seemed like problems were likely, it remains in good operational condition

(casing not inspected)




Case Studies: WR 10

- CRBG Well:
 - Drilled 2006, replaced failed well (2005)
 - 452 ft deep, screened 402-430 ft bgs
 - >1,000 gpm
- History/Issue
 - Failed well was grouted
 - Quickly start on 10
 - Soon developed WQ problems
 - Left in stand-by mode 15 yrs
 - In 2020, will ASR bubble push bad water away?



Case Studies: WR 10

- Findings: (1) Water quality had improved, (2) Screens clean, (3) Well productive, (4) Brush and disinfection only
- Outcome: (1) ASR is feasible, (2) City still needs to meet peak demand



Case Studies: WW5

- Emergency use only
- Aging infrastructure
- Suitable for ASR?
- Condition Assessment:
 - Collected Samples
 - Measured SC
 - Pulled Pump
 - Video Inspection



Case Studies: WW5

- Well moderately active
- Significant MIC (corrosion)
- Casing required cleaning prior to condition evaluation
- Cleaning process caused casing failure
- Well was re-built with new casing and seal
- Water was clean post-disinfection
- Well is now suitable for ASR




Case Studies: Lind 7

■ CRBG Well:

- Drilled 1980
- 1020 ft deep, open below 515 ft bgs

■ History/Issue

- 750 gpm loss
- 135 ft static drop
- WQ degradation



Case Studies: Lind 7


	Casing	Aquifer
Plate Ct (colonies/ml)	>1,500	>1,500
Anerobic growth (%)	<10	<10
Sulfate reducing bac	Neg	Neg
Fe/Mn oxidizing bac	Neg	Neg
E. Coli	Neg	Neg
Bac ID	Acintobacter venetianus Bacillus cereus; B. thuringiensis	
Microbe	Protozoa	

- Findings: oil feed, surface biology
- Outcome: keep it running, sample supply system, plan for new well in a few years

Case Studies: WR2

- Alluvial/CRBG Well:
 - Drilled 1962: 250 ft bgs; perforated 100-125 ft bgs in alluvial aquifer; open in basalt (>177 ft bgs)
 - Rebuild 2005: liner, screen, and perfs
 - 1,000 gpm

- History/Issue
 - Pre-Rebuild; sanding
 - Post-Rebuild; sanding, nitrate-N
 - 1,000 gpm to <250 gpm



Case Studies: WR2

- Basalt Well
 - Shallow well in developed area, WQ
 - Water Rights allow deeper completion
 - Downsizing to case, seal, advance = too small
- Outcome –
Decomm/Replace




Case Studies: WR 3

■ Basalt well with interbeds

- Drilled 1981: 585 ft deep; perfed 276-316 ft bgs; open 399 to BOH (irrigation)
- Rebuild 2001: screen and filter pack installed 238-574 ft bgs; perfed 269-394 ft bgs



■ History/Issue

- Pre-Rebuild; sanding, lower borehole collapse
- Post-Rebuild; sanding, WA degraded
- 2,500 gpm to <500 gpm



Case Studies: WR 3

- Findings: corroded, debris, last rebuild, options limited
- Outcome: decomm/replace



Legend: 1 – well location; 2 – drill rig; 3 – pipe rack; 4 – compressor(s); 5 – circ tank/frac tank (as needed); 6 – cuttings and water collection pit; 7 – Conveyance line; 8 – Conveyance line onto land application area for discharge water.

GURE: Approximate drilling site and equipment layout. Actual locations and equipment determined by selected drilling contractor in consultation with City.

Case Studies: MF 9

■ Findings

- ORP positive; LSI positive (high CaCO_3 ppt); highly active with Fe-Mg oxidizing bacteria
- Liner broken and offset
- Slots extremely overgrown
- Lower borehole filled with debris and not plumb

■ Outcome

- Can't fix (broken/displaced liner) or clean (slots)
- Replace well at better location in City

Take Homes

- Decide: maintain or run-to-failure?
- Problems are manageable if diagnosed correctly and addressed early
- Multiple rebuilds may be a **Red Flag**
- Original construction:
 - Avoid Slots
 - Telescope
 - Don't screen/perf shallow: prevent cascading water
- M&O:
 - Measure dynamic and static WL annually
 - Periodic SC measurement to track changes
 - Sample and/or physical inspection if SC drops or WQ changes occur
- Like a 20 y.o. car, sometimes you just have to call it a day.

Thank You for Your Time

- Kevin Lindsey, Principal Hydrogeologist, GeoEngineers, 509-209-2848
- Phil Brown, Principal Hydrogeologist/Owner, Northwest Groundwater Services, 503-313-5195