
REVIEWING BUILDING PLANS FOR CROSS CONNECTION CONTROL

JESSICA SHAW, DEPUTY PUBLIC WORKS DIRECTOR-UTILITIES

CITY OF WENATCHEE, WA

WHY REVIEW PLANS?


- Safe Drinking Water
- Correct backflow preventer
- Establish a good routine of testing
- CCC Education designers, contractors, plumbers and you
- Element 2: Evaluating new & existing services (WA)



COORDINATION WITH THE JURISDICTION HAVING AUTHORITY (JHA)

WAC 246-290-490 (1)(d)

Under this section, purveyors are not responsible for eliminating or controlling cross-connections within the consumer's water system. Under chapter **19.27** RCW, the responsibility for cross-connection control within the consumer's water system, i.e., within the property lines of the consumer's premises, lies with the authority having jurisdiction.



PLAN REVIEW PROCESS



Communication



Plan Review



Inspections






1111111111111111

COMMUNICATION

- Permitting Software Smartgov
- Plan Review Software BlueBeam
- Excel Spreadsheet
- Email
- Meetings



1 PLANNING Image: Comparison of the second	Type: E isplay Wo Cycle Info	rklist: O Adu	noject Name: SWI			tor: BOYER MTN DOOR & POOL IN		INC			CINE SPRINGS DR CHEE, WA 98801						
1 PLANNING Image: Comparison of the provance of t	Act Reqd	Next Cycle	Appvd in Cycle	Name	3	Workflow Step Status			Status Date	1	StatusBy		Assigned	Due Date	Required	Hours	
1 BUILDING BUILDING APPROVED W/CONDITIONS* • 03/07/2023 Chris Hanson BUILDING REVIEW 03/07/2023 Required for Approval 0			1	ENVIRONMENTAL	0	APPROVED*	•	-	02/28/2023	0	Jenni Rayson	99,	ENVIRONMENTAL	03/07/2023	Required for Approval	0	
			1	PLANNING	0	APPROVED*	•		03/07/2023	8	Mia Bretz	92	CURRENT PLANNING	03/07/2023	Required for Approval	0	
Step Maintenance			1	BUILDING	0	APPROVED W/CONDITIONS*	•		03/07/2023	8	Chris Hanson	90,	BUILDING REVIEW	03/07/2023	Required for Approval	0	
	Step	Maintenance													Total Ho	urs: 0.00	


Mai	n Notes Co	ontacts Contractors Parcels Fees De	tails	Submittals	Workflow	Cycles/Revie	ws Valuatio	ns Fixtures	Condition	Structures	Inspections	Bonds O	ther Requiremen	its Public
1.000	nit #: BPR-23-035 e: BPR-POOL	Status: ISSUED Contact: Project Name: SWIFT SPRINGS PH II Contractor				DLINC Site Ad		INE SPRINGS DR HEE, WA 98801						
• E	xpand Display	O Compress Display												
	Display Order	Inspection Type	Req	Deferred Re	ason Displa	ay Date Prima	ary Inspector	Inspection Sta	us <mark>State</mark>		Results Has Ad	ctions Has C	orrections	
8	1	POOL- REINFORCEMENT SETBACKS	V						R	equest			Ø	
Û	2	PLUMB-GROUND							R	equest			Ø	
Ū	3	POOL-FENCE ENCLOSURE							R	equest			Ø	
Ū	4	POOL-ACCESS ALARMS							R	equest			Ø	
Û	5	POOL-AUTO COVER							R	equest			Ø	
ũ	6	PW-BACKFLOW ASSEMBLY - POOL/SPA FILL							R	equest			Ø	
ũ	7	POOL-FINAL	v						R	equest			Ø	
C	Add												Total Hours:	0.00


What Types of Plans Should the CCS Review?



PLANS COME IN ALL SHAPES AND SIZES

- For premise, a site plan, civil plan, or civil site improvements may be adequate.
- In-premise, plumbing plan as well as equipment lists





REVIEWING PLANS – STEP 1 WHAT IS THE USE OF THE WATER SERVICE?

• Premise Isolation

- Severe & High Health Hazard
- Multi-story buildings over 30 feet
- Mobile home parks
- Multi-tenant commercial buildings
- Fire lines and private hydrants
- Non-residential





REVIEWING PLANS – STEP 3 IN-PREMISE OR FIXTURE/EQUIPMENT PROTECTION

- Landscape irrigation
- Fire sprinkler systems
- Boiler/hot water loops





COMMERCIAL BUILDING PLANS

- Restaurants
- Retail
- Grocery Stores
- Medical
- Hardware/home improvement





Chemical Feed



Ice Cream Scoop Washer



Industrial Washing Machine



Medical Equipment Washer





Grinder

Hot Water Loop & Boiler

COMMON COMMERCIAL EQUIPMENT

- Ice machine
- Water filtration system
- Post-mix pop, bar guns
- Espresso machine
- Commercial coffee brewer
- Commercial ice tea brewer
- Dish washer, ware washer, glass washer

- Ovens with steam option or self-cleaning
- Food steamer/ steam table
- Ice cream/gelato machine
- Pasta cooker
- Smoker
- Pressure washers
- Chemical feed systems



INDUSTRIAL BUILDING PLANS

- Usually the most complicated plans
- Industrial wastewater treatment or pretreatment systems
- Premise Isolation at a minimum
- Internal isolation of process water from domestic water

PUBLIC FACILITIES

- Schools, government offices, public works yards, lift stations, parks, pools,...
- Range from simple office buildings to more complex
- Premise Isolation at a minimum



MULTI-FAMILY BUILDING PLANS

- Duplexes
- Apartments
- Cottages
- Mobile Home Parks
- Townhomes



RESIDENTIAL BUILDING PLANS




- Radiant floor heat
- Fountain, pond, water feature
- Pool or hot tub
- Landscaping
- Fire sprinkler system

TENANT IMPROVEMENTS & CHANGES OF USE

- Less likely to have well drawn plans compared to new construction
- May not trigger a building permit
- Business License reviews may catch more than building permits





HOME BUSINESSES




REVIEWING PLANS – STEP 3 ARE THE BACKFLOW ASSEMBLIES SHOWN IN THE PLANS?

- Location
- Type of backflow assembly
- Installation details



PRE-APPROVED PLANS AND STANDARDS





https://www.wenatcheewa.gov/government/public-works/public-works-pre-approved-plans-and-policies

REVISED PLANS vs **PERMIT CONDITIONS**

• Problems

- Revised plans can be challenging to get owners/engineers to submit
- Permit conditions are often overlooked





REVIEWING PLANS – STEP 4 COMMUNICATING REQUIREMENTS OR CONDITIONS

- Language matters.
- Standard Requirements/Conditions
 - Call for an inspection (When? & Who?)
 - Backflow Assembly Test Before or after the inspection?
- Opportunities
 - Pre-application meetings
 - Pre-submittal meetings
 - Pre-construction meetings
 - Check-in with contractor/owner



INSPECTIONS & INITIAL TESTS

- Inspect promptly Don't wait for final
- Have a list of what to check
- Require the initial test as a permit condition
- Communicate corrections



LOCATION, LOCATION, LOCATION





-						
**		INSPE	CTION RESULTS		Page 1 of 2	6 /
		301 Yakima Stree	et, Suite 100, Wenatchee WA 98801 509-888-3244	Report	run on 03-28-2023	180
Application #	BPC-19-124	Application Type	BPC-NEW			• =
Parcel #	232034857052	Site Address	1229 WALLA WALLA AVE WENATCHEE			FE
pector	Inspection Type Da	nte Status	Comments			0.1
nes Frost	PW-BACKFLOW ASSEMBLY - HOT WATER 11 RECIRCULATION	-Aug-21 Comple	te			1201
Task Descrip	otion	Status	Comments			05
MINIMUM 1", DRAIN SHALL BE PROVIDED.		Pending				
	Correction(s)	: Description		Status	Status Date	t and the second se
HEIGHT, PRO	E CLEARANCE AND DPER PLACEMENT OF OR TESTING.	Pending				
	Correction(s)	: Description		Status	Status Date	
						and the second
General Obse	ervations	Pending				
	Correction(s)	: Description		Status	Status Date	
DRAIN PIPE	AND ASSEMBLY	Pending				
	Correction(s)	: Description		Status	Status Date	
BACKFLOW	ASSEMBLY TEST).	Pending				
	Correction(s)	: Description		Status	Status Date	
THERMAL I	EXPANSION PROVIDED.	Pending				
	Correction(s): Description		Status	Status Date	

Main Notes C	contacts Contractors Parcels Fees D	etails Subm	ittals Workflow	Cycles/Review	ws Valuations Fixtures	Conditions Struct	ures Inspections Bor	nds Oth	er Requiremen	ts Public Notices	ŝ.	
Permit #: BPC-17-16 Type: BPC-NEW	7 Project Name: HILTON GARDE	Contac EN INN Contra			OPMENT INC Site Address:	25 N WORTHEN ST WENATCHEE, WA 98801						
Expand Display	O Compress Display											
Display Orde	r Inspection Type	Req Deferre	d Reason	Display Date	Primary Inspector	Inspection Status	State	Results	Has Actions	Has Corrections		Î
8			REINSPECTION	03/29/2019	Dave Nichols	FAILED	Requires Re-Inspection	\$		1	9 📃	
8			REINSPECTION	03/28/2019	Dave Nichols	FAILED	Requires Re-Inspection	8		1	9 🔜	
6			REINSPECTION	03/27/2019	Dave Nichols	FAILED	Requires Re-Inspection	5		ł	9 📒	
8			REINSPECTION	03/26/2019	Dave Nichols	FAILED	Requires Re-Inspection	*		1	9 📒	
8			REINSPECTION	03/25/2019	Dave Nichols	FAILED	Requires Re-Inspection	۵.		4	9 📃	
8			REINSPECTION	03/21/2019	Dave Nichols	FAILED	Requires Re-Inspection	5		1	9 📃	
8			REINSPECTION	03/20/2019	Dave Nichols	FAILED	Requires Re-Inspection	8		1	9 💼	
6			REQUESTED	03/19/2019	Dave Nichols	FAILED	Requires Re-Inspection	5		1	9 📃	
8	PW-GREASE INTERCEPTOR INSTALLATION		REQUESTED	03/29/2019	Paula Salter	APPROVED	Complete		5	ł	9 📒	
8	MECHANICAL-TYPE I/II HOOD		REINSPECTION	03/18/2019	Dave Nichols	APPROVED	Complete	5	5	1	9 📃	
8			REQUESTED	01/04/2019	Scott York	PARTIAL APPROVAL	Requires Re-Inspection	۵.		1	9 📃	
8	PW-BACKFLOW ASSEMBLY - PREMISE		REINSPECTION	04/22/2019	Jessica Shaw	APPROVED	Complete		5	1	9 📃	
8			REQUESTED	03/29/2019	Jessica Shaw	PARTIAL APPROVAL	Requires Re-Inspection				9 📃	
8	PW-BACKFLOW ASSEMBLY - IN-PREMISE		REQUESTED	03/29/2019	Jessica Shaw	APPROVED	Complete	5	5	1	9 📒	
	PW-BACKFLOW ASSEMBLY - IRRIGATION		REQUESTED	04/22/2019	Jessica Shaw	APPROVED	Complete		5	ł	9 📒	-
										Total	Hours: 0.	0.00

ENFORCEMENT




- Corrections not completed wrong backflow preventer, wrong location, no drain on an RPBA, missing ladder from a vault, no supports, no initial test, failed test, etc...
- Enforcement Options
 - No certificate of occupancy
 - No water service
 - Fines



COORDINATING WITH UTILITIES & BUILDING DEPARTMENTS

- Have a plan & method for communication
- Clear responsibilities
- Standards
- Point of contact



PLAN REVIEW WRAP-UP

- Safe Drinking Water
- Element 2: Evaluating new & existing services
- Correct backflow preventer in the correct location
- Establish a good routine of testing
- CCC Education designers, contractors, plumbers and you





THANK YOU!

JSHAW@WENATCHEEWA.GOV

Photo by Paula Salter